


**New York State Department of Environmental Conservation**  
50 Wolf Road, Albany, New York 12233 - 7010



**Thomas C. Jorling**  
Commissioner

AUG 21 1990

SDMS Document



113699

Mr. Brian Blum  
Senior Scientist  
Geraghty and Miller Inc.  
125 East Bethpage Road  
Plainview, New York 11803


Dear Mr. Blum:

RE: Blydenburgh Road Landfill - Site No. 152002

As we discussed, I am requesting additional details concerning the repairs made to wells 4M1 and 4M2. Please provide me with construction drawings showing the lengths of riser replaced, the repair method (in detail) and the methods of access, backfill and grout. Also, a justification should be made for your statement that the integrity of the well has not been affected.

If you wish to discuss this, please call me at 518-457-1641.

Sincerely,

  
George W. Heitzman, P.E.  
Senior Engineer  
Bureau of Eastern Remedial Action  
Division of Hazardous Waste  
Remediation

cc: C. Weidner

GWH:mm  
bcc: T. Candela, Region 1  
M. Chen/R. Cozzy  
D. Morganelli, Region 1  
G. Heitzman

ISL 001 1726